

ELY ZONE Active Pits

jdh/ah/mr 1/20/21

Pit Name	Legal	Price/cyd	Notify Public Works of permit		Locked Key Needed	Comments/Special Conditions
			Y/N	District		
32. Eagles Nest	NW-SE 15-62-14	\$2.50	Y	4	Y	Land Department has Class 5 stockpile from 2013. PW Class 5 stockpile from 2016. Property line between adjacent property owner is bermed and property corner has been established. Care needed to prevent off site runoff.
33. Flaim Rd.	SE-SE 20-61-16	\$2.50	N	4	Y	All stockpiles for Land Dept use. Banks sloped from last user. Authorized training site for Vermilion Lake Fire Dept.
34. Hwy 169	SE-NE 18-60-16	\$2.50	N	4	N	Gravel/cobble hill west side of Hwy. 169, opposite Hilda Rd. Frequently used as wood yard. Entry road often under water, but solid. Almost depleted.
35. Kugler Ridge	NE-NE 34-61-15	\$2.50	N	4	N	L&M and PW have Class 5 stock piles from 2019 crushing. Clean sand, gravel, and small cobble. Do not confuse with Packa Pit (PW fee) at the beginning of the Kugler Ridge Road.
36. Mud Creek	NW-NE 8-62-14	\$2.50	Y	4	N	Sandy over ledge rock east side, crushable material west side. Difficult pit to develop, floor can be wet. Almost Depleted.
37. Murray Grade	SE-SW 30-62-14	\$2.50	N	4	N	North side of Murray RR grade, east of Murray Management Road crossing. Little use. Land Department stockpile crushed in 1999. Pit entrance bermed.
38. North Giant's Ridge	SE-NW 6-59-15	\$2.50	Y	6	N	Public Works sand screening. Clean fine gravel, sand, few cobbles. No gate. Soft floor.
39. Saari	SW-NE 20-61-13	\$2.50	N	4	N	On north side of access road into Spruce Lake, about 1 mile from County Road 490. Used for logger built harvest roads. Very little recent use.
40. Salo Road	SW-SW 24-60-14	\$2.50	Y	4	Y	Public Works last crushed in 2009. Crushable, but big boulders, excessive silty sand. Private gate.
41. Sherman	NW-NW 15-61-15	\$2.50	N	4	N	Mixed materials, suitable for crushing. Land Dept Class 5 stockpile from 2012 for Sherman Management Road Extension.
42. South Pike	NW-NE 22-60-16	\$2.50	Y	4	N	PW has Class 5 pile from 2018 crushing. Multipurpose pit on South Pike Management Road. Land Department stockpile west of road.

ELY ZONE
Active Pits


jdh/ah/mr 1/20/21

Pit Name	Legal	Price/cyd	Notify Public Works of Permit		Locked Key Needed	Comments/Special Conditions
			Y/N	District		
43. Skala	SE-SW 5-61-15	\$2.50	N	4	Y	Past PW crushing. Expandable to west, but sensitive recreation trail area, with ledge rock, and mature pine. Disposal site for PW blast-rock.
44. State Hwy #1	SW-NE 7-61-16	\$2.50	Y	4	Y	PW has Class 5 pile in pit from 2018 crushing. PW also uses for winter sand screening site. Tight floor space. Clean bedded outwash deposit of sand, gravel and cobbles. High bank but with a safety berm/ditch at top. Smaller sized screened rock for sale. Observe property lines west and north sides.
45. Wolf Lake	SW-SE 36-63-14	\$2.50	N	4	N	Clean sand and gravel with some cobble. Remote location, used by nearby cabin owners. High bank.



Ely Zone

Gravel Pits



● Land Dept Gravel Pits



© Copyright Saint Louis County
All Rights Reserved

Prepared By: **Land Department**
Data Resource Section
(218) 725-5000
www.co.st-louis.mn.us

Map Created: 3/4/2008


Location: M:/GRAVEL

Notes:

Disclaimer

This is a compilation of records as they appear in the Saint Louis County Offices affecting the area shown. This drawing is to be used only for reference purposes and the County is not responsible for any inaccuracies herein contained.

Tracking #: 10.10



St. Louis County MN

